

Queue Number 2840701

Transaction Date 06 Oct 2026, 13:43:29

Site Name
840 - Emirates AuctionsTransaction Number
79871472 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WDDHF5GB5A*****
Specification	Imported
Make	Mercedes
Model	E 350
Model Year	2010
Color	White
Mileage	132223 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	REAR CURTAIN NOT WORKING	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME LEFT SIDE FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخرى

03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK OPEN REFITTED, OIL SUMB BOLTS MISSING,SHAKING	الحالة النظرية للمحرك

04 Seats Condition		المقاعد
04.A Seat Condition	FRONT BOTH SIDE BACK COVER LOOSE	حالة المقاعد

05 Transmission Condition	الجير
---------------------------	-------

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED JERKING GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	RIGHT SIDE CRACKED	الضوء الخلفي
07.B Indicator & Hazard light	FRONT RIGHT SIDE NOT WORKING	الاشارات
08 Brake Condition		الفرامل
08.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS RUSTY SIGN OF FLOODED , CENTER CONSOLE BOX FOLDING COVER PORTION DAMAGED	اخرى
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	SWITCH FADED	مفتاح النافذه و الزجاج
10.D Roof Ceiling	PORTION LOOSE	بطانه السقف
10.E Sun Visor	BOTH SIDE PORTION DAMAGED	حاجب الشمس
10.F Steering Wheel and control buttons	EXTRA COVER	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae