

TEST CERTIFICATE

Site Number
Transaction Number

05.A Paint

840-Emirates Auctions 26903847 (CC10008) Transaction Date

11 May 2022, 14:36:44

Queue Number 312309

Chassis Number

1ZVFT82H155141220

Engine Number

Vehicle Class

Car

Manufacturer

Ford

Model

Mustang Roush

Model Year

2005

Color

Red

Mileage

171573 Miles

Fuel Type

Petrol

No. Of Cylinders

0

Specification

USA Imported

الصبغ

	0
DEFECT	MAI
01 Interior Condition	

RKS **01 Interior Condition** الحاله الداخليه 01.A Dash Board **CRACKED** لوحة القياده 01.B AC Condition **NOT WORKING** المكيف **02 Tires and Rims Condition** الاطارات 02.A Front Tyre BOTH SIDE 2016/2018 CRACKED & EXPIRED, MODIFIED الاطار الامامى 02.B Rear Tyre BOTH SIDE 2016/2015 CRACKED & EXPIRED, MODIFIED الاطار الخلفى **03 Transmission Condition** الجير **03.A DIFFERENTIAL REAR OIL LEAK** الدفرنشل 03.B Road Test **NOT CHECK** فحص على الطريق 03.C Visual Gear Box OIL LEAK, REFITTED حالة الجير النظرى Condition **04 Suspension System** ممتص الصدمات 04.A Arms FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS ازرع **BUSHES CUT** 05 Body جسم المركبة

BODY FULL STICKER PAINT CANNOT CHECK & PORTION

RUSTY

DEFECT	REMARKS	
05.B Bumper	MISALIGN	دعامية
05.C Trunk	NOT OPEN FOR CHECK	صندوق
05.D Rusty	UNDER BODY PARTS, SUSPENSION ,FLOOR GETTING RUSTY	صدأ
05.E Other	REAR BACK PANEL, QUATER PANEL REPAIRED	اخري
06 Chassis Condition		الشاصي
06.A Chassis	OK	الشاسيه
07 Engine Condition		المحرك
07.A Smoke	MINOR BLACK SMOKE	دخان
07.B Visual Engine Condition	OIL LEAK,REFITTED	حالة المحرك النظرى
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
09 Seats Condition		المقاعد
09.A Seat Condition	DRIVER SEAT SIDE COVER & SEAT DAMAGED	حالة المقاعد
10 Exhaust System		نظام العادم
10.A Other	CUT & REWLLDED	اخري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.