



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Sep 2021, 14:18:47
Transaction Number	90008779 (CC10006)	Queue Number	312309



Chassis Number	3GNEK18R2XG107945
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Tahoe
Model Year	1999
Color	Silver
Mileage	18639

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED, REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, FLOORING, CHASSIS FRAME, SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COMPLETELY RUST PROOFED	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Bonnet	REPAINTED & SHOCK WEAK	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME COMPLETELY THICK RUST PROOFED & PAINT	الشاسيه
03 Engine Condition		المحرك
03.A Other	OK & GETTING RUSTY	اخرى
03.B Mount	BUSHES CUT	كرسي
04 Seats Condition		المقاعد
04.A Other	BOTH SIDE SEAT BELT NOT WORKING	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير

DEFECT	REMARKS	
05.B Gear Box Mount	BUSHES CUT	كرسي الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2010 EXPIRED & BADLY CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2010/2009 EXPIRED & BADLY CRACKED	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WORN OUT	اخرى
08 Exhaust System		نظام العادم
08.A Other	MIDDLE MUFFLAR NUT MISSING & NOISY	اخرى
09 Lights		الاضاءة
09.A Head Light	OK	الاضاءة الرئيسية
09.B Other	OK	اخرى
10 Brake Condition		الفرامل
10.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CUT	ازرع
11.B Leaf Spring	BOTH SIDE BUSHES CUT & LEAF GETTING RUSTY	
12 Steering Condition		المقود
12.A Other	STABILIZER LINK BUSHES CUT	اخرى
12.B Tie Rod End	BUSHES CUT	مؤخرة الرودادات
13 Interior Condition		الاجزاء الداخلية
13.A Other	DASHBOARD COVER DAMAGED	اخرى
13.B Mirror	OK	المرايا
13.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.