



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jan 2023, 14:06:33
Transaction Number	24206710 (CC10006)	Queue Number	657316



Chassis Number	JTHBF1D28F5048820
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	IS 250
Model Year	2015
Color	Black
Mileage	212143 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Door Panel	PORTION DAMAGE.	لوحة بطانة الباب
01.B AC Condition	NOT WORKING PROPERLY .	المكيف
01.C Power Window Switch	SWITCH ASSEMBLY LOOSE.	مفتاح النافذه
01.D Air Bag	DAMAGE.	وسائد هوائية
02 Tires and Rims Condition		الاطارات
02.A Rear Tyre	BOTH SIDE 2021.	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2021.	الاطار الامامي
03 Body		جسم المركبة
03.A Paint	BODY PORTION REPAIRE ,PORTION REPAIRED .MINOR DENTS SCRATCHES.	الصبغ
03.B Rusty	UNDER BODY ,SUSPENSION PARS GETTING RUSTY .	صدأ
03.C Other	FRON BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER EREPAIRED.	اخرى
03.D Floor	PORTION DENT .	الارضية
03.E Fenders	REFITTED.REPAIRED ,REAR HIGH SIDE QUARTER PANEL ,FRONT RIGHT DOOR POST REPAIRED.	مدكار
03.F Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
03.G Fuel Tank	BRACKET DENT .	خزان الوقود
03.H Bonnet	REFITTED.	غطاء المحرك
03.I Sign of side accident		وجود مؤشر لحادث في الجانب
04 Brake Condition		الفرامل
04.A Brake Pedal	SPONGY .NOT WORKING.	دواسة الفرامل
04.B Hand Brake	WEAK.	فرامل اليد
05 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT & WARNING MESSAGE ON IN DASH BOARS CLUSTER .	ضوء تحذير
06 Transmission Condition		الجير
06.A Road Test	NOT CHECKED .	فحص علي الطريق
06.B Visual Gear Box Condition	NOT CHECKED. .	حالة الجير النظري
07 Engine Condition		المحرك
07.A Visual Engine Condition	,ABNORMAL NOISY.	حالة المحرك النظري
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CRAKED .	ازرع
09 Chassis Condition		الشاصي
09.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED. FENDER FRAME JOINT SLIGHTLY DETAHED.,	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.