

Queue Number

2855815

Transaction Date

12 Oct 2026, 09:48:14

Site Name

840 - Emirates Auctions

Transaction Number

62464785 (CC10026) (CC10026)



Vehicle Details

Chassis Number

JMYLYV75W3*****

Specification

GCC Specification

Make

Mitsubishi

Model

Pajero

Model Year

2003

Color

Black

Mileage

N/A Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , FRONT LEFT SIDE OUTER FENDER SKIRT DAMAGE	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATCHES FADED PORTION	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PARTS MINOR DENTS , MUDDY	الارضية
01.F Bumper	MISALIGN FIX BY SCREW DAMAGE , SCARTCHES , LEFT SIDE WATER NOZZLE DAMAGE	دعامية
01.G Trunk	NOT OPENING , OUTER LOCK PANEL DAMAGE	صندوق
01.H Door Handle &Lock	REAR RIGHT SIDE DOOR LOCK DAMAGE , NOT OPENING	مقابض الأبواب والأقفال
01.I Sign of front accident	BUMPER FRAME , FENDER FRAME , RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED , DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED , DENT , PORTION RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Other	AIR FILTER MODIFIED	اخرى
03.B Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , OIL LEAK	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION CRACK , EXTRA COVER	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST PIPE CUT REWELDED	تعديلات
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	ALL SYSTEM NOT CHECK , PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET , MUDDY	الحالة النظرية للجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2021 EXPIRED & LEFT SIDE DAMAGE ,	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2023 CRACK & RIGHT SIDE 2009 CRACK EXPIRED	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES , CENTER WHEEL HUB COVER MISSING	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08.B Tail Light	DAMAGE	الضوء الخلفي
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	BUSHES CRACK	أزرع
10.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
11 Steering Condition		المقود
11.A Tie Rod End	BOOT CRACK	مؤخرة الرودادات
12 Interior Condition		الحالة الداخليه
12.A Other	CENTER CONSOLE BOX PANEL WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
12.B AC Condition	NOT CHECK , GRILL PORTION LOOSE	المكيف
12.C Power Window Switch And Glass	MAIN SWICTH BUTTON PORTION FADED	مفتاح النافذه و الزجاج
12.D Floor Matting	DIRTY , EXTRA COVER	فرش الأرضيه
12.E Audio	LCD DISPLAY SCREEN WORN OUT , PANEL CONTROL LOOSE , ANTENNA MISSING	صوتيات
12.F Dash Board	PORTION DAMAGE	لوحة القيادة
12.G Sun Visor	RIGHT SIDE DAMAGE	حاجب الشمس
12.H Odometer reading	NOT CHECK	قراءة عداد المسافات
12.I Door Panel	PORTION REFITTED	لوحة بطانة الباب
12.J Steering Wheel and control buttons	WORN OUT , EXTRA COVER	عجلة القيادة وازرار التحكم
12.K Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae