



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>22 Jan 2023, 13:55:02</b>
Transaction Number	<b>86982881 (CC10009)</b>	Queue Number	<b>658754</b>



Chassis Number	<b>SALYK2EXOLA265667</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Range Rover</b>
Model	<b>Velar</b>
Model Year	<b>2020</b>
Color	<b>White</b>
Mileage	<b>32911 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED & REFITTED	مدكار
01.B Floor	FLOOR COVER PORTION DAMAGED	الارضية
01.C Bumper	FRONT ASSEMBLY REFITTED	دعامية
01.D Sign of front accident		وجود مؤشر لحادث في المقدمة
01.E Bonnet	REPAINTED PORTION REPAIRED & REFITTED	غطاء المحرك
01.F Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.G Other	FRONT BUMPER FRAME EXTENSION REFITTED , LEFT SIDE FENDER BRACKET DAMAGED	اخرى
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A AC Condition	OK	المكيف
02.B Other	GEAR LEVER TOP COVER MISSING	اخرى
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rear Tyre	BOTH SIDE 2019,	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2019,	الاطار الامامي

DEFECT	REMARKS	
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	CHECKED VISIBLE AREA OK	الشاصيه
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Visual Gear Box Condition	OK	حالة الجير النظرى
05.B Road Test	NOT CHECK	فحص علي الطريق
<b>06 Engine Cooling System</b>		<b>نظام تبريد المحرك</b>
06.A Radiator Condition	LOWER HOSE REPAIRED& COOLANT LEAK	حالة المبرد
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	OK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.