



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>27 Nov 2022, 12:26:02</b>
Transaction Number	<b>17655407 (CC10009)</b>	Queue Number	<b>630847</b>



Chassis Number	<b>WD4WG3E14L3623817</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>V class</b>
Model Year	<b>2020</b>
Color	<b>Black</b>
Mileage	<b>58942 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Floor	UNDER FLOOR FENDER CHASSIS FRAME FULLY COVERED CHECKED VISIBLE AREA	الارضية
01.B Paint	BODY PORTION REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2021,	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
<b>03 Steering Condition</b>		<b>المقود</b>
03.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	ABNORMAL NOISY	حالة المحرك النظري
04.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	CHECKED VISIBLE AREA ONLY/OK	الشاسيه
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A AC Condition	OK	المكيف

DEFECT	REMARKS	
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Visual Gear Box Condition	JERKING	حالة الجير النظرى
07.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Ball Joint	BOOT CUT	مفصل كروي
08.B Arms	LOWER ARM BUSH CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.