



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Jan 2023, 17:05:17
Transaction Number	42934128 (CC10006)	Queue Number	657853



Chassis Number	WVWBF21K7CW347507
Engine Number	
Vehicle Class	Car
Manufacturer	Volkswagen
Model	
Model Year	2012
Color	Blue
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Door Panel	FABRIC PORTION LOOSE	لوحة بطانة الباب
01.B AC Condition	NOT CHECK	المكيف
01.C Odometer reading	NOT CHECK	قراءة عداد المسافات
01.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.E Roof Ceiling	PORTION LOOSE	بطانه السقف
01.F Other	GEAR LEVER SIDE COVER PORTION CRACKED	اخرى
02 Body		جسم المركبة
02.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT , SCRATCHES, PORTION FADED,	الصبغ
02.B Doors	FRONT RIGHT SIDE & REAR BOTH SIDE NOT OPEN	أبواب
02.C Bumper	MISALIGN, PORTION DAMAGED	دعامية
02.D Trunk	NOT OPEN FOR CHECK	صندوق
02.E Floor	UNDER FLOOR COVERED, CHECKED ONLY VISIBLE AREA.	الارضية
02.F Door Handle & Lock	FRONT LEFT SIDE OUTER LOCK COVER MISSING	مقابض الأبواب والأقفال
02.G Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
03 Lights		الاضاءة

DEFECT	REMARKS	
03.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	NOT CHECK,OIL WET	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Suspension System		ممتص الصدمات
05.A Arms	LOWER ARM BUSH CUT	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,OIL LEAK	حالة المحرك النظرى
07 Chassis Condition		الشاصي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.