CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2982713 |
| Transaction Date | 13 Nov 2026, 15:07:43 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 69670984 (CC10026) (CC10026) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | 1GKS27KL1N******* |
| Specification | GCC Specification |
| Make | GMC |
| Model | Denali |
| Model Year | 2022 |
| Color | Black |
| Mileage | 142662 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 8 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Paint | BODY PAINT PULLY PROTECTED CLEAR FILM , PAINT CAN NOT CHECK , MINOR SCRATCHES | الصبغ |
| 01.B Rusty | UNDER FLOOR PARTS GETTING RUSTY | صدأ |
| 01.C Bumper | MISALIGN | دعامية |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | OK | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | PARTS GETTING RUSTY , MINOR OIL LEAK | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | الجير |
| 04.A Gear Box Visual Condition | OK | الحالة النظريه للجير |
| **05 Tires and Rims Condition** | | الاطارات |
| 05.A Front Tyre | BOTH SIDE 2024 | الاطار الامامي |
| 05.B Rear Tyre | BOTH SIDE 2024 | الاطار الخلفي |
| 05.C Rims Condition | MINOR DENT SCRATCHES | حالة الجنوط |
| **06 Interior Condition** | | الحاله الداخليه |
| 06.A AC Condition | OK | المكيف |

| Condition | Remarks | الحالة |
|---|---|---|
| 06.B Dash Board | PORTION WORN OUT | لوحة القياده |
| 06.C Roof Ceiling | PORTION WORN OUT | بطانه السقف |
| 06.D Door Panel | PORTION WORN OUT | لوحة بطانة الباب |
| 06.E Steering Wheel and control buttons | PORTION WORN OUT | عجلة القيادة وازرار التحكم |
| 06.F Gear Shifting Lever | PORTION WORN OUT | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**