

Queue Number

2873179

Transaction Date

15 Oct 2026, 16:43:19

Site Name

840 - Emirates Auctions

Transaction Number

79056574 (CC10013) (CC10011)



Vehicle Details

Chassis Number	MHFCX8EM2K*****
Specification	GCC Specification
Make	Toyota
Model	Innova
Model Year	2019
Color	Silver
Mileage	881216 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED,MISALIGN	مدكار
01.B Paint	BODY REPAIRED REPAINTED,MINOR DENT SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR FULLY MUDDY FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	الارضية
01.E Bumper	MISALIGN , LOGO MISSING	دعامية
01.F Bonnet	REFITTED,MISALIGN	غطاء المحرك
01.G Other	VEHICLE USE FOR TAXI	اخرى
01.H Trunk	REFITTED,INNER COVER PORTION LOOSE	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD REPAIRED ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED FRAME GETTING RUSTY MUDDY	الشاسيه
02.B Other	FOR MORE INSPECTION MAKE STEAM WASH FOR RECHECK	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	MUDDY , DIRTY , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION CUT,REAR SEATS LOOSE BACK COVER PORTION DAMAGED	حالة المقاعد
---------------------	---	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Other	DENT	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR JERKING , MUDDY , DIRTY , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025,LEFT WORN OUT	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2025,RIGHT 2023 CRACK	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	BOTTLE CAP MISSING / PART DAMAGED	ازرع المساحات والشفرة
09 Lights		الاضاءة
09.A Head Light	LENS FADED,LEFT SIDE PORTION CRACKED	الاضاءة الرئيسية
09.B Tail Light	LEFT SIDE PORTION CRACK	الضوء الخلفي
09.C Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
09.D Fog light	FADED NOT WORKING	كشف الضباب
10 Brake Condition		الفرامل
10.A Brake Pedal	SPONGY	دواسة الفرامل
10.B Hand Brake	WEAK	فرامل اليد
11 Suspension System		ممتص الصدمات
11.A Shock Absorber	SIGN OF LEAK	ممتص الصدمات
11.B Arms	ARM BUSHES DRY CRACK	ازرع
11.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
12 Steering Condition		المقود
12.A Tie Rod End	BOOT CUT	مؤخرة الروداد
13 Interior Condition		الحاله الداخليه
13.A Other	INTERIOR PARTS DIRTY GETTING RUSTY SIGN OF FLOODED	اخرى
13.B AC Condition	NO COOLING	المكيف
13.C Dash Board	PORTION WORN OUT,DAMAGED	لوحة القيادة
13.D Roof Ceiling	DIRTY WORN OUT	بطانه السقف
13.E Odometer reading	CLUSTER PANEL COVER FADED	قراءة عداد المسافات
13.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
13.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
13.H Gear Shifting Lever	SHIFT LOCK COVER MISSING	ذراع نقل السرعات

Condition	Remarks	الحالة
14 Engine Cooling System		نظام تبريد المحرك
14.A Radiator Cooling Fan	SAFETY COVER PORTION DAMAGED	مروحة تبريد المبرد
14.B Coolant tank	WATER EMPTY	خزان التبريد
15 Battery Condition		حالة البطارية
15.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae