

### **TEST CERTIFICATE**

Site Number
Transaction Number

03.A Road Test

**04 Seats Condition** 

Condition

03.B Visual Gear Box

840-Emirates Auctions 14456614 (CC10006) Transaction Date

18 Sep 2022, 16:10:21

Queue Number

590551



Chassis Number SALLDHAD81A607253

Engine Number

Vehicle Class Car

Manufacturer Land Rover

Model **Defender** 

Model Year 2001

Color White

Mileage 64003 Km

Fuel Type Petrol

No. Of Cylinders

Specification European Imported

**DEFECT** REMARKS

O1 Body		جسم المركبة
01.A Paint	BODY TOTALY REPAINTED, PORTION REPAIRED, MINOR DENTS, SCRATCHES	الصبغ
01.B Fenders	REFITTED	مدكار
01.C Doors	REFITTED	أبواب
01.D Bonnet	REFITTED	غطاء المحرك
01.E Floor	UNDER BODY PARTS RUSTPROOFED.	الارضية
01.F Other	REFURBISHED VEHICLE.	اخري
<b>02 Interior Condition</b>		الحاله الداخليه
02.A Dash Board	PORTION DAMAGED	لوحة القياده
02.B AC Condition	NO AC IN THIS VEHICLE.	المكيف
03 Transmission Condition		الجير

NOT CHECK

REFITTED OIL LEAK

03.C Propeller Shaft FRONT LEFT SIDE ROMANO LEAK

ناقل الحركة

فحص علي الطريق

حالة الجير النظرى

المقاعد

DEFECT	REMARKS	
04.A Seat Belt	LEFT SIDE NOT WORKING	حزام الأمان
04.B Seat Condition	LOOSE	حالة المقاعد
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
06 Chassis Condition		الشاصي
06.A Chassis	CHASSIS NUMBER REPUNCHED	الشاسيه
07 Engine Condition		المحرك
07.A Visual Engine Condition	REFITTED ,ENGINE OVER HEAT ,COOLANT LEAKING.	حالة المحرك النظرى
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	SUSPENSION SYSTEM REFITTED.	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

## **Test Certificate**











**Possession Certificate:** 66885797 SALLDHAD81A607253 Chassis No: Vehicle Make: LAND ROVER Vehicle Model: **DEFENDER** Vehicle Class: Light Vehicle **Body Type:** PICK-UP Fuel: Benzene Color: White **Drive Direction:** Dimensions: (H x W x L) --x--x-**Current Odometer:** 64003 Kms. Origin: Great Britain Model Year: 2001 Engine Size: 3000 CC Gear Type: Manual Engine No: 17H36153 Horse 182 Power: Axles No: 2 Cylinders: 8 No Of No Of Seats: 4 Doors: G. V. W. : 1800 Kas. **Empty** 1630 Kas. Weight:

Certificate Number :		5-TAS-2022-17692103				
Inspection Date :		22-0	22-09-2022			
Certificate Print Date :		22-0	22-09-2022			
Services :		Regi	Registration Test			
Vehicle Te	esting Partner:	Tasj	eel			
Vehicle Testing Center:		Tasjeel Al Aweer				
Total Time Taken :		20 min 39 sec				
Appointment :	ent Ref					
Start	14:33		End Time:	14:54		
Time :			Token No.:	3		
Lane :	02		Prints No:	1		
Attempt :	1					

#### **Parameter Readings**

Service brake imbalance on front axle

5%

Service brake imbalance on rear axle 3 %

Parking brake imbalance between LHS and RHS 9 % Vehicle on Petrol CO Reading 2.23 %

Vehicle on Petrol HC Reading 48 PPM VOL

#### **Inspection Findings**

Defects	Issue	Severity
Fuel tank and pipings fuel pipe leaking	Leaking	Major
Front Seat belts fix front left side seat belt	Defective	Major

Discrepancies	Old Value	New Value	Verified
Incorrect information about GCC specific Incorrect information about GCC specifications with No Document	Yes	No	
Seats Incorrect Number of Seats	4	6	
Doors and Locks Incorrect Number of doors (does not require doc)	5	3	
Engine Cylinders Incorrect number of cylinders	8	4	
Engine Size Discrepancy in Engine Size	3000	2500	

# **Payment Details**

Inspection Performed by<br/>34600Payment Method<br/>VTP Credit AccountTransaction Number<br/>17692103Service Fees<br/>AED 170 Collected on 22/09/2022Parking Slot No<br/>--Service Name<br/>Registration TestAttemptReceived by<br/>Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

• Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرَت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30 يوح من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

## **Test Certificate**











**Possession Certificate:** 66885797 SALLDHAD81A607253 Chassis No: Vehicle Make: LAND ROVER Vehicle Model: **DEFENDER** Vehicle Class: Light Vehicle **Body Type:** PICK-UP Fuel: Benzene Color: White **Drive Direction:** Dimensions: (H x W x L) --x--x-**Current Odometer:** 64003 Kms. Origin: Great Britain Model Year: 2001 Engine Size: 3000 CC Gear Type: Manual Engine No: 17H36153 Horse 182 Power: Axles No: 2 Cylinders: 8 No Of No Of Seats: 4 Doors: G. V. W. : 1800 Kas. **Empty** 1630 Kas. Weight:

Certificate Number :		5-TAS-2022-17692103				
Inspection Date :		22-0	22-09-2022			
Certificate Print Date :		22-0	22-09-2022			
Services :		Regi	Registration Test			
Vehicle Te	esting Partner:	Tasj	eel			
Vehicle Testing Center:		Tasjeel Al Aweer				
Total Time Taken :		20 min 39 sec				
Appointment :	ent Ref					
Start	14:33		End Time:	14:54		
Time :			Token No.:	3		
Lane :	02		Prints No:	1		
Attempt :	1					

#### **Parameter Readings**

Service brake imbalance on front axle

5%

Service brake imbalance on rear axle 3 %

Parking brake imbalance between LHS and RHS 9 % Vehicle on Petrol CO Reading 2.23 %

Vehicle on Petrol HC Reading 48 PPM VOL

#### **Inspection Findings**

Defects	Issue	Severity
Fuel tank and pipings fuel pipe leaking	Leaking	Major
Front Seat belts fix front left side seat belt	Defective	Major

Discrepancies	Old Value	New Value	Verified
Incorrect information about GCC specific Incorrect information about GCC specifications with No Document	Yes	No	
Seats Incorrect Number of Seats	4	6	
Doors and Locks Incorrect Number of doors (does not require doc)	5	3	
Engine Cylinders Incorrect number of cylinders	8	4	
Engine Size Discrepancy in Engine Size	3000	2500	

# **Payment Details**

Inspection Performed by<br/>34600Payment Method<br/>VTP Credit AccountTransaction Number<br/>17692103Service Fees<br/>AED 170 Collected on 22/09/2022Parking Slot No<br/>--Service Name<br/>Registration TestAttemptReceived by<br/>Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

• Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرَت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30 يوح من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.