



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>06 Oct 2021, 17:49:17</b>
Transaction Number	<b>83388041 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>SCBCF63W39C062327</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Bentley</b>
Model	<b>Continental</b>
Model Year	<b>2009</b>
Color	<b>White</b>
Mileage	<b>140916 N/A</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY PORTION REPAIRED &REPAINTED	الصبغ
01.B Floor	FLOOR HAVE MINOR DENT	الارضية
01.C Bumper	REPAINTED	دعامية
01.D Fenders	REAR RIGHT FENDER PORTION REPAIRED,REPAINTED&FENDER REFITTED	مدكار
01.E Bonnet	REAR TRUNK NOT WORKING PROPERLY &BONNET REFITTED	غطاء المحرك
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Warning Light	WARNING ON IN DISPLAY	ضوء تحذير
02.B Head Light	OK	الاضاءة الرئيسية
<b>03 Interior Condition</b>		<b>الاجزاء الداخلية</b>
03.A AC Condition	OK	المكيف
03.B Mirror	LEFT FOLDING NOT WORKING	المرايا
03.C Other	CENTRE CONSOLE BOX SLIDING DOOR BROKEN	اخرى
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH 2019 WORNOUT	الاطار الامامي
04.B Rear Tyre	BOTH 2019	الاطار الخلفي
04.C Other	RIMS HAVE SCRATCHES	اخرى
<b>05 Engine Condition</b>		<b>المحرك</b>

DEFECT	REMARKS	
05.A Other	MINOR OIL LEAK	اخرى
<b>06 Wipers and Arms</b>		<b>المساحات</b>
06.A Other	NOT WORKING	اخرى
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Gear Box	OK	الجير
<b>08 Chassis Condition</b>		<b>الشاصي</b>
08.A Chassis	VISABLE AREA OK	الشاسيه
<b>09 Brake Condition</b>		<b>الفرامل</b>
09.A Break Pads	WORN OUT	سفايف الرامل
<b>10 Steering Condition</b>		<b>المقود</b>
10.A Axel	REAR LEFT AXLE GREASE LEAK	اكسلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.