CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2990336
Transaction Date	14 Nov 2026, 12:47:34
Site Name	840 - Emirates Auctions
Transaction Number	65059272 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1GTEK14R2W*******
Specification	GCC Specification
Make	GMC
Model	Sierra
Model Year	1998
Color	Black
Mileage	105806 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION RUSTY	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION REPAIRED DENT	الارضية
01.F Bumper	MISALIGN,PORTION DENT	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BUMPER ASSEMBLY, BEND REAPIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	BOTH SIDE CHASSIS REPAIRED COMPLETELY THICK RUST PROOFED, BOTH SIDE CHASSIS BEND PORTON DENT	الشاسيه
02.B Chassis Number	FRAME NUMBER NOT VISIBLE, DOOR STICKER WORNOUT, NOT MATCHING WITH GLOW BOX VIN	رقم القاعدة
03 Engine Condition		المحرك
03.A Other	AIR INTAKE MODIFIED	اخري
03.B Engine Visual Condition	OIL LEAK DRIPPING OPEN REFITTED MODIFIED SHAKING	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Belt	NOT WORKING	حزام الأمان
04.B Seat Condition	BOTH SIDE ADJUSTMENT NOT WORKING,SIDE COVER LOOSE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	CUT REWELDED MODIFIED	اخري
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR OIL LEAK OPEN REFITTED MODIFIED JERKING, GEAR BOX ASSEMBLY WELDED REPAIRED	الحالة النظريه للجير
06.B Propeller Shaft	FRONT MISSING	ناقل الحركة
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	MISSING	ازرع المساحات والشفرات
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED, ARMS BEND	ازرع
09.B Other	SUSPENSION MODIFIED	اخري
10 Steering Condition		المقود
10.A Other	MODIFIED LOOSE HARD TO TURN	اخري
11 Interior Condition		الحاله الداخليه
11.A Other	INETRIOR PARTS GETTING RUSTY,CENTER CONSOLE BOX LOCK DAMAGED,INTERIOR MODIFIED	اخري
11.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING & CENTER MIRROR PORTION FADED	المرايا
11.C AC Condition	NOT WORKING	المكيف
11.D Power Window Switch And Glass	BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.E Dash Board	PORTION CRACKED LOOSE	لوحة القياده
12 Engine Cooling System		نظام تبريد المحرك
12.A Radiator Condition	MODIFIED	حالة المبرد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**