CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2890778
Transaction Date	20 Oct 2026, 13:48:52
Site Name	840 - Emirates Auctions
Transaction Number	30104145 (CC10009) (CC10012)



Vehicle Details

Chassis Number	JN6BE6DS2G*******
Specification	GCC Specification
Make	Nissan
Model	NV350
Model Year	2016
Color	White
Mileage	379226 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS CHASIS SUSPENSION RUSTY	صدأ
01.C Floor	FLOOR PORTION RUNNING BOARD, REAR BOTH SIDE WHEEL ARCH QUARTER PANEL RUSTY HOLES DAMAGED	الارضية
01.D Bumper	GRILL MISALIGN	دعامية
01.E Sign of front accident	FRONT BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL QUARTER PANEL WHEEL ARCH REPAIRED RUSTY	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	BOTH SIDE CHASSIS RUSTY BULGED PORTION HOLE, FRONT CROSS MEMBER BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED, GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER , PORTION DAMAGED , LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2025 , LEFT SIDE DAMAGED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	RUSTY	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	RIGHT SIDE LENS FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
08 Interior Condition		**الحاله الداخليه**
08.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
08.B AC Condition	OK	المكيف
08.C Power Window Switch And Glass	RIGHT SIDE PANEL LOOSE	مفتاح النافذه و الزجاج
08.D FLoor Matting	EXTRA COVER , PORTION DAMAGED	فرش الأرضيه
08.E Dash Board	WORN OUT , PORTION CRACK	لوحة القياده
08.F Door Panel	WORN OUT	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT , HORN NOT WORKING	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae