

Queue Number 2909791

Transaction Date 26 Oct 2026, 14:29:23

Site Name
840 - Emirates AuctionsTransaction Number
65440529 (CC10009) (CC10025)

Vehicle Details

Chassis Number	WDDUG6FB1G*****
Specification	GCC Specification
Make	Mercedes
Model	S 400
Model Year	2016
Color	White
Mileage	56856 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	REAR RIGHT SIDE REPAINTED PORTION REPAIRED , REAR LEFT SIDE PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Bumper	MISALIGNNG	دعامية
01.G Windshield	FRONT CRACK	زجاج
01.H Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLKE AREA ONLY/OK	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY OIL WET	الحالة النظرية للمحرك
------------------------------	-----------------------------	-----------------------

04 Seats Condition المقاعد

04.A Seat Belt	FRONT LEFT SIDE COVER PORTION DAMAGED	حزام الأمان
04.B Seat Condition	BACK COVER DAMAGED	حالة المقاعد

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	FRONT PORTION DAMAGED	ازرع المساحات والشفرات
08 Interior Condition		الحالة الداخليه
08.A Other	CENTER CONSOLE BOX SLIDING COVER NOT WORKING	اخرى
08.B AC Condition	OK	المكيف
08.C Power Window Switch And Glass	REAR RIGHT SIDE SWITCH PORTION LOOSE , CURTAIN SWITCH NOT WORKING	مفتاح النافذه و الزجاج
08.D Roof Ceiling	PORTION LOOSE , MINOR CUT	بطانه السقف
08.E Door Panel	LEATHER PORTION DAMAGED LOOSE	لوحه بطانة الباب
08.F Steering Wheel and control buttons	WORN OUT , LOOSE	عجلة القيادة وازرار التحكم
08.G Sunroof	NOT WORKING PROPERLY	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae