

Queue Number 2890763

Transaction Date 20 Oct 2026, 16:41:02

Site Name
840 - Emirates AuctionsTransaction Number
70145719 (CC10013) (CC10025)

Vehicle Details

Chassis Number	JN1BT2MWXG*****
Specification	GCC Specification
Make	Nissan
Model	X-Trail
Model Year	2016
Color	Black
Mileage	420581 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED REFITTED , REAR RIGHT SIDE PORTION DAMAGED	مدكار
01.B Paint	BODY PORTION REPAINTED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED DENT	الارضية
01.E Bumper	MISALGN , PORTION DAMAGED	دعامية
01.F Trunk	FIBER PANT NOT CHECK	صندوق
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS PORTION GETTING RUSTY MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	اخرى
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Other	INNER ELECTRIC WIRE WORN OUT UNSAFE	اخرى
03.C Engine Visual Condition	COMPONENTS REFITTE D, PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CUT , SIDE COVER PORTION LOOSE , DRIVER SEAT ADJUSTMENT NOT HANDLE NOT WORKING	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR JERKING , COMPONENTS REFITTED , OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MMINOR DENT SCRATCHES / NUT MISSING	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	BOTTLE CAP MISSING	اخرى
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Other	SUSPENSION PARTS REFITTED	اخرى
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX PORTION CRACK , INTERIOR PARTS GETTING RUSTY MODIFIED PARTS REFITTED WATER FLOODED	اخرى
10.B AC Condition	LOW COOLING	المكيف
10.C Audio	DISPLAY FADED	صوتيات
10.D Dash Board	LEFT SIDE PART COVER MISSING	لوحة القيادة
10.E Roof Ceiling	LOOSE	بطانه السقف
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT , PORTION CRACK	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	PART COVER MISSING	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	BOTTLE CAP MISSING	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae