



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Jan 2022, 18:18:33</b>
Transaction Number	<b>95813574 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1GTN29EC6EZ223444</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>GMC</b>
Model	<b>Sierra</b>
Model Year	<b>2014</b>
Color	<b>Silver</b>
Mileage	<b>151910 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT LEFT SIDE PORTION REPAIRED, REPAINTED	مدكار
01.B Pillars	LEFT SIDE B/PILLAR OUTER PANEL REPAIRED, REPAINTED	القوائم
01.C Floor	REAR CARRIOR BOX PORTION REPAIRED & REPAINTED	الارضية
01.D Other	REAR LEFT SIDE QUATER PANEL, FLOOR REPAIRED	اخرى
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A Steering Wheel and control buttons	COVER PORTION DAMAGED	عجلة القيادة وازرار التحكم
02.B AC Condition	OK	المكيف
02.C Mirror	OK	المرايا
02.D Sun Visor	BOTH SIDE MIRROR COVER MISSING & RIGHT SIDE MIRROR CRACKED	حاجب الشمس
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Engine Condition	OIL LEAK	حالة المحرك
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Gear Box	OIL LEAK	الجير
04.B Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	SEAT COVER PORTION DAMAGED	حالة المقاعد
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	CHASSIS FRAME COMPLETELY THICK RUST PROOFED & RUSTY	الشاسيه
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Head Light	OK	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>08 Wipers and Arms</b>		<b>المساحات</b>
08.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2017 CRACKED	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي
<b>10 Exhaust System</b>		<b>نظام العادم</b>
10.A Modification	MODIFIED	تعديلات
<b>11 Suspension System</b>		<b>ممتص الصدمات</b>
11.A Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
<b>12 Steering Condition</b>		<b>المقود</b>
12.A Other	FRONT STABILIZER LINK BOOT CUT	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.