



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 24 Nov 2022, 13:12:18 |
| Transaction Number | 50394156 (CC10006) | Queue Number | 629896 |



| | |
|------------------|--------------------------|
| Chassis Number | JTFLU71J9G7037414 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Toyota |
| Model | Land Cruiser |
| Model Year | 2016 |
| Color | Gold |
| Mileage | 367909 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|---|------------------------|
| 01 Tires and Rims Condition | | الاطارات |
| 01.A Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |
| 01.B Front Tyre | BOTH SIDE 2021 | الاطار الامامي |
| 02 Suspension System | | ممتص الصدمات |
| 02.A Leaf Spring | BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY | |
| 03 Transmission Condition | | الجير |
| 03.A Gear Box Mount | BUSH CRACKED | كرسي الجير |
| 03.B Road Test | NOT CHECK | فحص علي الطريق |
| 03.C Visual Gear Box Condition | REFITTED | حالة الجير النظري |
| 04 Interior Condition | | الحاله الداخليه |
| 04.A Sun Visor | PORTION DAMAGED | حاجب الشمس |
| 04.B AC Condition | OK | المكيف |
| 05 Lights | | الاضاءة |
| 05.A Brake Light | BOTH SIDE NOT WORKING | نور الفرامل |
| 06 Body | | جسم المركبة |

| DEFECT | REMARKS | |
|------------------------------|---|--------------------|
| 06.A Rusty | UNDER BODY PARTS, SUSPENTION , CHASSIS FRAME GETTING RUSTY | صدأ |
| 06.B Paint | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES, | الصبغ |
| 07 Chassis Condition | | الشاسي |
| 07.A Chassis | CHASSIS FRAME COMPLETELY THICK RUST PROOFED PORTION RUSTY & REAR CROSSMEMBER RUSTY WEAK, HOLE | الشاسيه |
| 08 Engine Condition | | المحرك |
| 08.A Visual Engine Condition | REFITTED, SUMB OIL LEAK | حالة المحرك النظري |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.