CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3007867
Transaction Date	18 Nov 2026, 16:41:13
Site Name	840 - Emirates Auctions
Transaction Number	70330837 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1C3CCCAB3F*******
Specification	Imported
Make	Chrysler
Model	200
Model Year	2015
Color	Black
Mileage	106073 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS MUDDY PORTION MINOR DENT	الارضية
01.E Bumper	MISALIGN,PORTION CRACKED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER BULK HEAD ASSEMBLY REFITTED, LEFT SIDE FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS MUDDY PORTION COVERED CHECKED VISIBLE AREA OK	الشاسيه
02.B Other	STEAM WASH REMOVE FRONT UNER CHASSIS COVER FOR RECHECK PROPERLY	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	REFITTED GETTING RUSTY,SHAKING	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	REFITTED GETTING RUSTY,JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	FRONT BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2025 & RIGHT SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Tail Light	LEFT SIDE DAMAGED	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY, Water/Flood	اخري
08.B Mirror	LEFT SIDE COVER PORTION MISSING & CENTER MIRROR PORTION FADED	المرايا
08.C AC Condition	NOT COOLING	المكيف
08.D Audio	NOT WORKING	صوتيات
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae