

Queue Number 2815076

Transaction Date 30 Sep 2026, 16:34:49

Site Name
840 - Emirates AuctionsTransaction Number
78524705 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WDB2201761*****
Specification	GCC Specification
Make	Mercedes
Model	S 600
Model Year	2004
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED DIRTY	الارضية
01.F Bumper	MISALIGN , FRONT BUMPER PORTION MODIFIED	دعامية
01.G Windshield	REAR CURTAIN NOT WORKING / FRONT TINTED	زجاج
01.H Bonnet	REFITTED	غطاء المحرك
01.I Other	FRONT ASSEMBLY REFITTED , BODY KIT MODIFIED ACUTAL VEHICLE MERCEDES 600	اخرى
01.J Trunk	AUTO SWICTH NOT WORKING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION COVERED ,OILY & MUDDY , CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	UPPER COVER MISSING	اخرى
03.B Engine Visual Condition	OPEN & REFITTED , MISFIRING , SHAKING , OIL LEAK ,PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Catalytic Converter	CUT REWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR JERKING DELAY SHIFTING REFITTED ,OIL LEAK , DIPSTICK MISSING ,PARTS GETTING RUSTY	الحالة النظره للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	LEFT SIDE 2023 , RIGHT SIDE 2024	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2023 , RIGHT SIDE 2022	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	BRACKET REPAIRED	الاضاءة الرئيسية
08.B Tail Light	RIGHT SIDE CRACK	الضوء الخلفي
08.C Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
08.D Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	REFITTED / BOLT MISSING	ممتص الصدمات ازرع اخرى عمود التوازن و مثبت عمود التوازن النظام الهيدروليكي
09.B Shock Absorber	MINOR LEAK	
09.C Arms	ARM BUSHES DRY CRACK	
09.D Other	SUSPENSION PARTS REFITTED	
09.E Stabilizer Bar And Link Rod	BOOT CUT	
09.F Hydraulic System	NOT WORKING DISCONNECTED	
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER LEATHER LOOSE , INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	BOTH SIDE FOLDING NOT WORKING & LEFT SIDE GLASS MIRROR FADED / PORTION CRACK	المرايا
10.C AC Condition	OK	المكيف
10.D Power Window Switch And Glass	REAR BOTH SIDE QUARTER GLASS SAFETY SEAL RUBBER WORN OUT	مفتاح النافذه و الزجاج
10.E Audio	REAR LCD SCREEN FADED	صوتيات
10.F Dash Board	LEATHER REPLACED ,PORTION LOOSE	لوحة القيادة
10.G Roof Ceiling	PORTION LOOSE	بطانه السقف
10.H Sun Visor	BOTH SIDE COVER MIRROR DAMAGED,LOOSE	حاجب الشمس
10.I Odometer reading	CLUSTER NOT WORKING	قراءة عداد المسافات
10.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.K Sunroof	NOT WORKING	فتحت سقف
10.L Gear Shifting Lever	PANEL PORTION LOOSE	ذراع نقل السرعات

Condition	Remarks	الحالة
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	BOTTLE CAP DIRTY (SIGN OF WATER MIX WITH OIL)	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae