



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>11 Nov 2022, 11:55:36</b>
Transaction Number	<b>37991498 (CC10010)</b>	Queue Number	<b>621235</b>



Chassis Number	<b>KMHE241GXJA484270</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Hyundai</b>
Model	<b>Sonata</b>
Model Year	<b>2018</b>
Color	<b>Silver</b>
Mileage	<b>87881 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OK	حالة الجير النظري
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2020/2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Bonnet	REFITTED	غطاء المحرك
03.B Other	FRONT BUMPER FRAME ,BULKHEAD,FENDER FRAME ,RADIATOR SUPPORT REPAIRED.	اخرى
03.C Floor	UNDER BODY COVERED ,CHECKED ONLY VISIBLE AREA .	الارضية
03.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
03.E Fenders	REFITTED.	مدكار
03.F Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>04 Chassis Condition</b>		<b>النشاصي</b>

DEFECT	REMARKS	
04.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED.	الشاسيه
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OK	حالة المحرك النظرى
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Axle	BOOT GREASE LEAKING.	اكسلات
<b>07 Interior Condition</b>		<b>الحاله الداخليه</b>
07.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



✓ PASS

Vehicle  
Registration



Plate Details :	Y 38810 Dubai Private
Chassis No :	KMHE241GXJA484270
Vehicle Make :	HYUNDAI
Vehicle Model :	SONATA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	87878 Kms.
Origin : South Korea	Model Year : 2018
Gear Type : Automatic	Engine Size : 2400 CC
Engine No : G4KEJD0017...	Horse 112
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 2015 Kgs.	Empty 1585 Kgs.
	Weight :

Certificate Number :	1-TAS-2022-18068710		
Inspection Date :	10-11-2022		
Certificate Print Date :	10-11-2022		
Services :	Renewal Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	13 min 27 sec		
Appointment Ref Number :	--		
Start Time :	14:21	End Time :	14:34
Lane :	01	Token No. :	188
Attempt :	1	Prints No. :	1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption (Rate last 12 Months)

23026 KM	2370 L	8082 AED	5.7 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 12 %	Service brake imbalance on rear axle 0 %	Parking brake imbalance between LHS and RHS 5 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 0 PPM VOL			

## Inspection Remarks:

FRONT LEFT WHEEL HOUSING, SIDE-MEMBER FRAME OUTSKIRT REPAIRED, FRONT BUMPER FRAME BULK HEAD FENDERS REPAIRED MINOR GEAR OIL LEAK

## Payment Details

Inspection Performed by 30544	Payment Method Cash	Transaction Number 18068710	Service Fees AED 170 Collected on 10/11/2022
Parking Slot No --	Service Name Renewal Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

