



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Jan 2023, 11:31:59</b>
Transaction Number	<b>18837316 (CC10006)</b>	Queue Number	<b>657753</b>



Chassis Number	<b>JN1BN61C33W002092</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Sunny</b>
Model Year	<b>2003</b>
Color	<b>White</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		
		<b>المحرك</b>
01.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OILLEAK ,REFITTED .	حالة المحرك النظري
01.B Mount	CRACKED.	كرسي
<b>02 Transmission Condition</b>		
		<b>الجير</b>
02.A Road Test	NOT CHECKED .	فحص علي الطريق
02.B Visual Gear Box Condition	NOT CHECKED & REFITTED OIL LEAK .	حالة الجير النظري
<b>03 Interior Condition</b>		
		<b>الحاله الداخليه</b>
03.A AC Condition	NOT CHECKED .	المكيف
03.B Odometer reading	NOT CHECKED .	قراءة عداد المسافات
03.C Dash Board	DAMAGE .	لوحة القيادة
03.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
03.E Other	GLOVE BOX DAMAGE .	اخرى
<b>04 Steering Condition</b>		
		<b>المقود</b>
04.A Steering Box	OIL LEAK .	جهاز المقود

DEFECT	REMARKS	
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
05.B Sign of back accident		وجود مؤشر لحادث في الخلف
05.C Sign of front accident		وجود مؤشر لحادث في المقدمة
05.D Bumper	MISALIGN ,PORTION DAMAGE	دعامية
05.E Paint	BODY PORTION REPAIRED ,REPAINTED ,DENTS SCRATCHES ,PORTION FADED ,PORTION RUSTY .	الصبغ
05.F Other	MI,FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	اخرى
05.G Floor	PORTION DENT . BACK PANEL ,QUARTER PANEL REPAIRED.	الارضية
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2019 CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2016 EXPIRED ,CRACKED .	الاطار الخلفي
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Shock Absorber	LEAK ,	ممتص الصدمات
07.B Arms	LOWER ARM BUSHESCRACKED .	ازرع
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED.	الشاسيه
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.