



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	20 Nov 2021, 17:54:58
Transaction Number	64768835 (CC10006)	Queue Number	312309



Chassis Number	JN1CC13C28T006217
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Tiida
Model Year	2008
Color	Black
Mileage	459622 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES , PORTION FADED, RUSTY ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Bumper	REPAINTED & MISALIGN	دعامية
01.E Rusty	UNDER BODY PARTS & SUSPENTION GETTING RUSTY	صدأ
01.F Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
01.G Trunk	REPAIRED & REPAINTED	صندوق
01.H Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT & REAR BACK PANEL REPAIRED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Gear Box	OIL LEAK	الجير
03.C Gear Box Mount	BUSHES CUT	كرسي الجير

DEFECT	REMARKS	
04 Seats Condition		المقاعد
04.A Other	SEAT COVER CRACKED	اخرى
05 Lights		الاضاءة
05.A Other	ALL NOT CHECK	اخرى
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2017 CRACKED & EPAIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2015 EXPIRED,CRACKED	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	NOT CHECK	ازرع المساحات والشفرات
08 Engine Condition		المحرك
08.A Engine Condition	ENGINE NOT START POWER TRAIN & LIGHT NOT CHECK	حالة المحرك
09 Brake Condition		الفرامل
09.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY	
11 Interior Condition		الحاله الداخليه
11.A AC Condition	NOT CHECK	المكيف
11.B Dash Board	DAMAGED	لوحة القيادة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.