CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934087	Transaction Date	03 Nov 2026, 12:49:58
Site Name	840 - Emirates Auctions	Transaction Number	66400536 (CC10026) (CC10026)



Vehicle Details

Chassis Number	1FA6P8TH0H*******
Specification	Imported
Make	Ford
Model	Mustang
Model Year	2017
Color	White
Mileage	69329 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.D Bumper	MISALIGN , PORTION DAMAGE FIXS BY SCREW	دعامية
01.E Bonnet	REPAINTED PORTION REPAIRED , MISALIGN NOT CLOSING , REFITTED	غطاء المحرك
01.F Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED, DENT & CHASSIS LOWER EDGE SLIGHTLY BEND	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Exhaust System		**نظام العادم**
05.A Modification	EXHAUST PIPE PORTION CUT OPEN & MIDDLE PORTION BADLY CUT	تعديلات
06 Transmission Condition		**الجير**

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
07.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF WATER FLOODED	اخري
10.B AC Condition	OK , GRILL DAMAGE	المكيف
10.C Dash Board	PORTION WORN OUT	لوحة القياده
10.D Odometer reading	CLUSTER DISPLAY PORTION FADED	قراءة عداد المسافات
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	COOLANT LOW LEVEL	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae