





### Test Certificate

|                     |                        |                    |             |
|---------------------|------------------------|--------------------|-------------|
| Site Number         | : 840-EMIRATES AUCTION | Plate Code         | : 0         |
| Transaction Number  | : 20381238             | Plate Category     | : PRIVATE   |
| Transaction Date    | : 27 JUL 2020 15:09:38 | Plate Number       | : 005846 EA |
| Queue Number        | : 201228               | Import Doc. Ref.   | :           |
| Chassis Number      | : WAUML44E65N005846    | Manufacturer/Model | : AUDI/A8   |
| Engine Number       | :                      | Model Year         | : 2005      |
| Vehicle Class       | : LIGHT VEHICLE        | Vehicle Color      | : WHITE     |
| Service / Indicator | : DSC AUCTION          |                    |             |

### Statement of Vehicle Condition

| Defect                                   | Result | Remarks   |
|--|--------|---|
| AUTOMATIC TEST:                          |        |   |
| 13 Brake System                          |        | الفرامل   |
| 13.04 - Brake Test                       | Passed | فحص الفرامل   |
| 14 Exhaust Gas Test                      |        | الغاز العادم والكربون   |
| 14.01 - Exhaust Gas Test                 | Passed | فحص الغاز العادم-الكربون  |
| 16 Side Slip Test                        |        | فحص ميزانية الاطارات  |
| 16.01 - Side Slip Test                   | Passed | فحص ميزانية الاطارات  |
| VISUAL TEST:                             |        |   |
| 01 Lights                                |        | الانوار   |
| 01.02 - Tail Lights                      |        | الانوار الخلفية<br>BOTH LENS CRACKED//RIGHT SIDE<br>NUMBER PLATE LIGHT NOT WORKING                        |
| 02 Steering And Suspension System        |        | عجلة القيادة ونظام التوصيلات  |
| 02.04 - Steering Ball Joints, Boots      |        | وصلات عمود عجلة القيادة<br>FRONT LEFT BALL JOINT BOOT<br>CRACKED/& SUSPENSION SENSOR BUSH<br>WORNOUT      |
| 02.11 - Shock Absorbers                  |        | مخمد الصدمات<br>FRONT SHOCK MODIFIED/REPLACED WITH<br>SHOCK LOWERING SPRING                               |
| 02.13 - Stub Axle Assemblies, Boots      |        | المحور<br>AXLE BOOT CRACKED   |
| 02.15 - Suspension Crack Or Bend, Bushes |        | التوصيلات<br>FRONT SUSPENSION SUBFRAME PARTLY<br>BROKEN.  |
| 04 Tires Rims                            |        | الاطارات والعجلات   |
| 04.01 - Front Left And Right Hands Tires |        | الاطارات الامامية<br>DOT 2017 REAR SUNSHADE DEFECTIVE   |
| 04.08 - Spare Tires                      |        | لاطار الاحتياطي<br>SPARE TIRE PUNCTURE//FRONT RIGHT RIM<br>CENTER COVER MISSING & INCOMPLETE<br>TIRE BOLT |
| 05 Body                                  |        | الهيكل  |
| 05.02 - Paint                            |        | الصبغ<br>PARTLY DENT/SCRATCHES/START<br>BUTTON DEFECTIVE  |
| 05.03 - Doors                            |        | الابواب<br>TRUNK DOOR CLOSING SWITCH/REAR<br>LEFT INDIVIDUAL WINDOW SWTICH<br>DEFECTIVE                   |
| 05.05 - Bumpers                          |        | الدعمية<br>FRONT BUMPER/RADIATOR<br>FRAME/BONNET/FENDER REPAIRED  |
| 05.07 - Floor                            |        | الارضية<br>BOTH RUNNING BOARD DENT  |
| 06 General Items                         |        | الاشياء العامة  |



### Test Certificate

|                     |                        |                    |             |
|---------------------|------------------------|--------------------|-------------|
| Site Number         | : 840-EMIRATES AUCTION | Plate Code         | : 0         |
| Transaction Number  | : 20381238             | Plate Category     | : PRIVATE   |
| Transaction Date    | : 27 JUL 2020 15:09:38 | Plate Number       | : 005846 EA |
| Queue Number        | : 201228               | Import Doc. Ref.   | :           |
| Chassis Number      | : WAUML44E65N005846    | Manufacturer/Model | : AUDI/A8   |
| Engine Number       | :                      | Model Year         | : 2005      |
| Vehicle Class       | : LIGHT VEHICLE        | Vehicle Color      | : WHITE     |
| Service / Indicator | : DSC AUCTION          |                    |             |

### Statement of Vehicle Condition

|  |   |                               |
|--|---|-------------------------------|
| 06.12 - Seats Condition And Seats Fixing   | SEAT/CEILING & OTHER COMPONENT<br>WORNOUT & DIRTY/CONSOLE BOX<br>PARTLY BROKEN      | المقاعد وحالتها وتثبيتها      |
| 06.14 - Transmission Condition   | OIL COOLER OIL LEAK & GEAR OIL STAIN/<br>&SHIFTING LEVER MONITOR LIGHT<br>DEFECTIVE | حالة ناقل الحركة              |
| 06.16 - Engine Condition, Smoke  | ENGINE DRIVE BELT WORNOUT/OIL STAIN   | حالة المحرك - الدخان          |
| 07 Remarks   |   | ملاحظات                       |
| 07.04 - Others   | 381312 KM   | ملاحظات اخرى                  |
| 09 Auction   |   | الفحص الكامل                  |
| 09.06 - Chassis Ok   |   | الشاسي جيد                    |
| 09.14 - Sign Of Front Accident   |   | أثر حادث في مقدمة المركبة     |
| 09.18 - A/C Not Cooling  |   | عطل في المكيف                 |
| 09.24 - Digital Display Damaged/Warning Lights   | WARNING LIGHTS ON   | عطل في لوحة التحكم الالكتروني |
| 09.25 - Body Repainted   | BODY PORTION REPAINTED  | أثر صيغ في المركبة            |
| The Test Certificate Shows the test Result at the time of inspection only.<br>Tasjeel is not responsible for any hidden defects. |   |                               |