

Queue Number 2180657

Transaction Date 07 Feb 2026, 12:28:08

Site Name
840 - Emirates AuctionsTransaction Number
89941048 (CC10009) (CC10019)

Vehicle Details

Chassis Number	1FMSK7DH8L*****
Specification	Imported
Make	Ford
Model	Explorer
Model Year	2020
Color	Silver
Mileage	65480 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT BOTH SIDE & REAR LEFT SIDE REPAINTED PORTION REPAIRED,	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR COVERED DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME WHEEL ARCH , LEFT SIDE FIRE WALL REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED BEND PORTION DENT, SUSPECT REPLACED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	SING OF COOLANT WATER LEAK	اخرى
03.B Engine Visual Condition	SHAKIN PARTS REFITTED, GETTING RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED, GETTING RUSTY	الحالة النظرية للجير
--------------------------------	-------------------------------	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LEFT SIDE LENS FADED	الاضاءة الرئيسية
07 Interior Condition		الحالة الداخلية
07.A AC Condition	OK	المكيف
07.B Power Window Switch And Glass	FRONT LEFT SIDE NOT WORKING & SWITCH DAMAGED	مفتاح النافذه و الزجاج
07.C Roof Ceiling	PORTION LOOSE	بطانه السقف
07.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
07.E Air Bag	DAMAGED	وسائد هوائية
07.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae