

Queue Number 2884403

Transaction Date 19 Oct 2026, 17:41:44

Site Name
840 - Emirates AuctionsTransaction Number
61891066 (CC10013) (CC10011)

Vehicle Details

Chassis Number	5N1BT3AB5P*****
Specification	Imported
Make	Nissan
Model	Rogue
Model Year	2023
Color	Black
Mileage	77032 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	3

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED, MINOR DENTS SCRATCHES, PORTION FADED GETTING RUSTY	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED PORTION DENTS RUST PROOFED	الارضية
01.F Bumper	MISALIGN , SCRATCHES	دعامية
01.G Roof	ROOF, ROOF RAIL PORTION REPAIRED REPAINTED	السقف
01.H Bonnet	REFITTED	غطاء المحرك
01.I Pillars	RIGHT SIDE A, BOTH SIDE B / PILLAR REPAIRED	القوائم
01.J Trunk	FIBER PAINT NOT CHECK REFITTED, LUGGAGE SHADE MISSING	صندوق
01.K Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD , INNER FENDER FRAME REPAIRED , ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Chassis Number	CORRECT VIN NUMBER (5N1BT3BA5PC849147) / VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Belt	REAR RIGHT SIDE NOT WORKING	حزام الأمان
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST SYSTEM MODIFIED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , HOUSING BOLT MISSING , OIL PAN DENT , OL LEAK , PARTS GETTING RUSTY , MINOR JERKING	الحالة النظرية للجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025 GETTING WORN OUT	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025 GETTING WORN OUT	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	STILL ON,RIGHT SIDE LENS GETTING FADED	الاضاءة الرئيسية
08.B Indicator & Hazard light	FRONT RIGHT SIDE INDICATOR LIGHT LENS FADED	الاشارات
08.C Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	DENT	ممتص الصدمات
09.B Arms	ARM BUSHES DRY CRACK	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
10.B AC Condition	OK	المكيف
10.C Dash Board	LEATHER PORTION REFITTED WORN OUT	لوحة القيادة
10.D Air Bag	DAMAGED	وسائد هوائية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

