

Queue Number	2827631	Transaction Date	07 Oct 2026, 13:21:03
Site Name	840 - Emirates Auctions	Transaction Number	40178309 (CC10010) (CC10010)



Vehicle Details

Chassis Number	KL1JD5CE9K*****
Specification	GCC Specification
Make	Chevrolet
Model	Aveo
Model Year	2019
Color	White
Mileage	201073 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		
جسم المركبة		
01.A Paint	BODY REPAINTED,PORION REPAIRED,MINOR DENT SCRATCHES, PORTON RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	FLOOR PORTION DENT ,RIGHT SIDE RUNNING BOARD DENT DETACHED .	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED.	دعامية
01.E Bonnet	REFITTED .	غطاء المحرك
01.F Trunk	REFITTED .	صندوق
01.G Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL , COMPARTMENT, QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		
الشاسي		
02.A Chassis	CHASSIS COMPLETE COVERED OILY MUDDY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		
المحرك		
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
04 Seats Condition		
المقاعد		
04.A Seat Condition	DIRTY PORTION LOOSE.	حالة المقاعد
05 Transmission Condition		
الجير		
05.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED WORN OUT PUNCTURE.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED WORN OUT PUNCTURE.	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	الزرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR CONDITION DIRTY PORTION RUSTY ,SIGN OF FLOODED.	اخرى
09.B Mirror	CENTER MIRROR FADED.	المرآيا
09.C AC Condition	NOT CHECKED.	المكيف
09.D Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae