



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>18 May 2022, 13:03:53</b>
Transaction Number	<b>57239006 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTEHJ09J355117847</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Land Cruiser</b>
Model Year	<b>2005</b>
Color	<b>White</b>
Mileage	<b>275395 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT LEFT SIDE & REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
01.B Doors	FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED & REAR RIGHT SIDE PORTION REPAINTED	أبواب
01.C Paint	BODY PORTION REPAIRED,REPAINTED & MINOR DENT SCRATCHES & PORTION FADED	الصبغ
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	OK	المكيف
02.B Audio	AUDIO SCREEN CRACKED	صوتيات
02.C Steering Wheel and control buttons	MINOR WORN OUT	عجلة القيادة وازرار التحكم
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
04.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Smoke	WHITE SMOKE	دخان
05.B Visual Engine Condition	OIL LEAK	حالة المحرك النظري
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Shock Absorber	FRONT & REAR SHOCK ABSORBER OIL LEAK	ممتص الصدمات
06.B Arms	REAR CONTROL ARM BUSHES CRACKED	ازرع
<b>07 Seats Condition</b>		<b>المقاعد</b>
07.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Indicator & Hazard light	FRONT LEFT SIDE INDICATOR LIGHT BROKEN	الاشارات
<b>09 Steering Condition</b>		<b>المقود</b>
09.A Steering Oil	OIL LEAK	زيت المقود
09.B Steering Boot	BOOT CUT	ربلة المقود
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	OK	الشاسيه
<b>11 Brake Condition</b>		<b>الفرامل</b>
11.A Hand Brake	WEAK	فرامل اليد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.