CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934033
Transaction Date	06 Nov 2026, 16:18:37
Site Name	840 - Emirates Auctions
Transaction Number	66776585 (CC10008) (CC10011)



Vehicle Details

Chassis Number	WDDGF4HB8D*******
Specification	Imported
Make	Mercedes
Model	C 250
Model Year	2013
Color	White
Mileage	297759 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	FRONT RIGHT SIDE PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER BODY COVERED ,COVER PORTION DAMAGED PARTS MISSING	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED REFITTED ,OPENING HANDLE SAFETY LOCK MISSING ,SHOCK WEAK	غطاء المحرك
01.H Sign of front accident	FENDER FRAME ,RADIATOR SUPPORT ,BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY /OK	الشاسيه
02.B Other	FOR PROPERLY INSPECTION NEED TO REMOVE FENDER COVER UNDER COVER	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,OIL LEAK, OPEN REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECK ,OIL LEAK ,PARTS GETTING RUSTY ,REFITTED	الحالة النظريه للجير
05.B Propeller Shaft	FLANGE RUBBER CRACK	ناقل الحركة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	RIGHT SIDE 2024 CRACK,LEFT SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT,SCRATCHES,HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE BRACKET DAMAGED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,CENTER CONSOLE BOX BACK SIDE DAMAGED	اخري
10.B AC Condition	NOT CHECK ,REAR GRILL DAMAGED	المكيف
10.C Power Window Switch And Glass	MAIN SWITCH FADED ,DRIVER WINDOW OPEN	مفتاح النافذه و الزجاج
10.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae