

Queue Number 2836088

Transaction Date 05 Oct 2026, 15:45:06

Site Name
840 - Emirates AuctionsTransaction Number
82092840 (CC10010) (CC10010)

Vehicle Details

Chassis Number JTDBR42E38*****
 Specification GCC Specification
 Make Toyota
 Model Corolla
 Model Year 2008
 Color Red
 Mileage 533688 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE & FRONT LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION FADED,PORTION RUSTY..	الصبغ
01.C Doors	REAR BOTH SIDE & FONT LEFT SIDE DOOR REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.F Bumper	MISALIGN , SCRATCHES	دعامية
01.G Roof	REPAINTED PORTION REPAIRED , BOTH SIDE TRAIL STRIP GETTING WORN OUT	السقف
01.H Sign of back accident	BACK PANEL BEND	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED GETTING RUSTY , MUDDY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	LOWET MOUNT CRACK	كرسي
03.B Smoke	WHITE	دخان
03.C Engine Visual Condition	PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET,SHAKING ,ABNORMAL NOISY.	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET,GET JERKING.	الحالة النظرية للجير
--------------------------------	---	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	RIGHT SIDE 2023 CRACK LEFT SIDE 2025	الاطار الخلفي
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	WATER TANK COVER MISSING	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE NOT WORKING , LEFT SIDE LENS FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION DAMAGE , RIGHT SIDE SIGN OF SCRATCHES	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX WORN OUT , INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
09.B AC Condition	NOT COOLING	المكيف
09.C Floor Matting	DIRTY	فرش الأرضية
09.D Dash Board	PORTION WORN OUT , MELTED	لوحة القيادة
09.E Sun Visor	LOOSE	حاجب الشمس
09.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
09.H Engine Start Button	KEY DAMAGE , FIX BY TAPE	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

