

Queue Number

2670006

Transaction Date

25 Aug 2026, 12:40:36

Site Name

840 - Emirates Auctions

Transaction Number

93026147 (CC10013) (CC10019)



Vehicle Details

Chassis Number

NLAFC5671J*****

Specification

GCC Specification

Make

Honda

Model

Civic

Model Year

2018

Color

Black

Mileage

153579 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED MUDDY, PORTION DENTS	الارضية
01.D Bumper	MISALIGN	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY PORTION GETTING RUSTY	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE COVER FOR RECHECK	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	COVERED MUDDY DIRTY PARTS GETTING RUSTY ABNORMAL NOISY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد
---------------------	-----------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY MUDDY	الحالة النظرية للجير
--------------------------------	---	----------------------

05.B Road Test

NOT CHECKED

فحص علي الطريق

06 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 WORN OUT	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION DAMAGED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنايير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES DRY CRACK	أزرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	CENTER MIRROR PORTION FADED	المرايا
10.C AC Condition	NOT COOLING	المكيف
10.D Dash Board	GETTING FADED PORTION WORN OUT	لوحة القيادة
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae