

TEST CERTIFICATE

Site Number
Transaction Number

05.A Visual Engine Condition

06 Chassis Condition

840-Emirates Auctions

74282185 (CC10010)

Transaction Date

15 Mar 2023, 12:10:07

حالة المحرك النظرى

الشاصي

Queue Number

687990



Chassis Number SCA689X09KU110187

Engine Number

Vehicle Class Car

Manufacturer Rolls Royce

Model Cullinan

Model Year 2019

Color Gold

Mileage 4297 Km

Fuel Type Petrol

No. Of Cylinders 12

Specification GCC Specification

| DEFECT | REMARKS | |
|-----------------------------------|---|-------------------|
| 01 Interior Condition | | الحاله الداخليه |
| 01.A AC Condition | ОК | المكيف |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Front Tyre | BOTH SIDE 2018 EXPIRED | الاطار الامامي |
| 02.B Rear Tyre | BOTH SIDE 2018 EXPIRED | الاطار الخلفي |
| 03 Body | | جسم المركبة |
| 03.A Paint | BODY OK | الصبغ |
| 03.B Floor | UNDER BODY COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA. | الارضية |
| 04 Transmission Condition | | الجير |
| 04.A Road Test | NOT CHECK | فحص علي الطريق |
| 04.B Visual Gear Box Condition | ОК | حالة الجير النظرى |
| 05 Engine Condition | | المحرك |

ОК

DEFECT REMARKS

06.A Chassis

CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA OK.

الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا
 تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من