

Queue Number

2855826

Transaction Date

10 Oct 2026, 12:46:20

Site Name

840 - Emirates Auctions

Transaction Number

42944767 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WAURVB4H8B*****
Specification	GCC Specification
Make	Audi
Model	A8
Model Year	2011
Color	White
Mileage	117062 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED,FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE PORTION REPAIRED REPAINTED,REAR LEFT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED / COVERED PORTION DAMAGED / DIRTY	الارضية
01.F Bumper	MISALIGN,PORTION CRACK SCRATCHES	دعامية
01.G Bonnet	PORTION REPAIRED REPAINTED,REFITTED	غطاء المحرك
01.H Trunk	NOT OPER FROM REMOTE,REAR SWITCH	صندوق
01.I Door Handle & Lock	FRONT LEFT SIDE DOOR OUTER LOCK HANDLE LOOSE	مقابض الأبواب والأقفال
01.J Vehicle Color	WHITE / BLACK	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------


03 Engine Condition

المحرك

03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	OIL LEAK DRIPPING , OIL PAN DENT , COMPONENTS REFITTED , PARTS GETTING RUSTY , MUDDY , OILY , DIRTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد



Condition	Remarks	الحالة
04.A Seat Condition	FRONT BOTH SEAT BACK COVER LOOSE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST MODIFIED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR JERKING ,OIL WET , MUDDY , PARTS GETTING RUSTY , OILY	الحالة النظرية للجير
06.B DIFFERENTIAL	MOUNT RUBBER CRACK	الدفرنشل
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS GETTING FADED,LEFT SIDE PORTION CRACKED	الاضاءة الرئيسية
08.B Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
08.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Other	SUSPENSION PARTS REFITTED	اخرى
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CUP HOLDER COVER PORTION DAMAGED LOOSE,INTERIOR PORTION MODIFIED REFITTED GETTING RUSTY	اخرى
10.B Mirror	SWITCH CRACK,BOTH SIDE AUTO FOLDING NOT WORKING,CENTER VIEW MIRROR BACK COVER MISSING	المرايا
10.C AC Condition	OK	المكيف
10.D Roof Light	FRONT PANEL MISALIGN,SUNGLASS BOX DAMAGED	أنارة السقف
10.E Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH NOT WORKING	مفتاح النافذه و الزجاج
10.F Dash Board	PORTION LOOSE	لوحة القيادة
10.G Roof Ceiling	PORTION MINOR LOOSE	بطانه السقف
10.H Sun Visor	RIGHT SIDE BRACKET DAMAGED	حاجب الشمس
10.I Odometer reading	CLUSTER PANEL DISPLAY GETTING FADED	قراءة عداد المسافات
10.J Door Panel	REAR LEFT SIDE PART MISSING	لوحة بطانة الباب
10.K Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.L Sunroof	NOT WORKING,SWITCH PORTION DAMAGED	فتحت سقف
10.M Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10.N Engine Start Button	GETTING WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae