



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **23 May 2023, 17:01:36**  
 Transaction Number **75831954 (CC10006)** Queue Number **719202**



Chassis Number **WVWRV1AJ4FM200810**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Volkswagen**  
 Model **Jetta**  
 Model Year **2015**  
 Color **White**  
 Mileage **105588 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.B Floor	UNDER FLOOR COVERD, CHECKED VISIBLE AREA ONLY	الارضية
01.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,	الصبغ
01.D Bonnet	REPAINTED,PORTION REPAIRED	غطاء المحرك
01.E Fenders	RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	مدكار
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الامامي
<b>03 Chassis Condition</b>		<b>الشاسي</b>
03.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Roof Ceiling	LOOSE	بطانه السقف
04.B AC Condition	NOT WORKING	المكيف
<b>05 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	OIL WET	حالة الجير النظري
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	OIL WET	حالة المحرك النظري
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	LOWER ARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Warning Light	WARNING LIGHT ON IN DISPALY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.