CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934032
Transaction Date	02 Nov 2026, 14:28:10
Site Name	840 - Emirates Auctions
Transaction Number	66012101 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WP1ZZZ92ZD*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2013
Color	White
Mileage	388227 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.D Door Handle &Lock	HANDLE SENSOR MISSING	مقابض الأبواب والأقفال
01.E Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY COVERED MUDDY OILY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER CHASSIS FLOOR FENDER COVERS FOR RECHECK	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED/ ENGINE NOT START ALL SYSTEM NOT CHECKED, GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED, NOT CHECKED	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	NOT CHECKED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Other	SUSPNSION REFITTED	اخري
09 Steering Condition		المقود
09.A Steering Oil	MINOR OIL LEAK	زيت المقود
09.B Tie Rod	DAMAGED	رودات
09.C Tie Rod End	RIGHT SIDE MOUNT DAMAGED	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	REAR LEFT SIDE CIGARETTE TRY LOOSE /INNER PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
10.B Dash Board	LEATHER.PORTION LOOSE	لوحة القياده
10.C Roof Ceiling	PORTION LOOSE	بطانه السقف
10.D Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Sunroof	CONTROL PANEL ASSEMBLY	فتحت سقف
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae