



Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 26873550 Plate Category : PRIVATE

Transaction Date : 07 JUN 2021 12:01:40 Plate Number : 074921 EA

Queue Number : 344653

Chassis Number : JN8AY2NY7E9074921 Manufacturer/Model : NISSAN/PATROL

Engine Number :

Model Year : 2014

Import Doc. Ref.

Vehicle Class : LIGHT VEHICLE

Vehicle Color : BLACK

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفر امل
13.04 - Brake Test	Passed		فحص الفر امل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
VISUAL TEST:			
02 Steering And Suspension System			عجلة القيادة ونظام التوصيلات
02.10 - Ties Rods, Bushes, Center Link, Left And Right		TIE ROD BOOTS CRACK	ربلات ذراع التوجيه
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		ALL TIRES DOT 2020	الاطارات الامامية
05 Body			الهيكل
05.02 - Paint		BODY SCRATCHES & DENTS/ PAINT THICKNESS FROM 80 TO 225 MICRONS	الصبغ
05.08 - Chassis (Frame)		CHASSIS FRAME SANDBLASTED & REPAINTED	الشاصية
06 General Items			الاشياء العامة
06.12 - Seats Condition And Seats Fixing		INTERIOR PARTLY WORN OUT	المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		ОК	حالة ناقل الحركة
06.16 - Engine Condition, Smoke		OK	حالة المحرك - الدخان
07 Remarks			ملاحظات
07.04 - Others		49196 KMS/ ROLL CAGE INSTALLED	ملاحظات اخرى
09 Auction			الفحص الكامل
09.02 - Need Wheel Alignment			بحاجة الى ميز انية العجلات
09.24 - Digital Display Damaged/Warning Light	s	LOW WASHER FLUID LIGHT ON	عطل في لوحة التحكم الالكتروني
09.02 - Need Wheel Alignment			- جة الى ميز انية العجلات

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

مهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط سجيل غير مسئولة عن العيوب الخفية

Test Certificate









Plate Details: JN8AY2NY7E9074921 Chassis No : Vehicle Make: NISSAN Vehicle Model: PATROL Vehicle Class: Light Vehicle **Body Type:** STATION Fuel: Benzene Color: Black **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 49197 Kms. Origin: Japan Model Year: 2014 Gear Type: Engine Size: 3500 CC Engine No: vk5693894... Horse Power: 400 Axles No: 2 Cylinders: No Of Doors: 4 No Of Seats: 8 G. V. W.: Empty Weight: 2300 Kgs. 3100 Kas.

Certificate Number: 5-TAS-2021-14377801 Inspection Date: 10-06-2021 Certificate Print Date : 10-06-2021 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Emirates Auction Total Time Taken: 10 min 5 sec Appointment Ref Number : --Start Time: 13:21 End Time: 13:31 Lane: Token No.: 14 Attempt : Prints No: 1 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



4919 KM

Distance per

year



per year



vear

1.3 ton
Carbon footprint
per year

Parameter Readings

Service brake imbalance on front axle

6%

Service brake imbalance on rear axle 2 %

Parking brake imbalance between LHS and RHS Vehicle on Petrol CO Reading 0.01%

Vehicle on Petrol HC Reading

14 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	5600	

Inspection Remarks: CHASSIS FRAME SANDBLASTED & REPAINTED

Payment Details

Inspection Performed by 59460 Parking Slot No Payment Method
VTP Credit Account
Service Name
Registration Test

Transaction Number
14377801
Attempt
1

Service Fees
AED 170 Collected on 10/06/2021
Received by
Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا



لقانون السير و المرور أ2 لسنة 1995 This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995