CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2707138
Transaction Date	02 Sep 2026, 12:26:30
Site Name	840 - Emirates Auctions
Transaction Number	85093185 (CC10009) (CC10012)



Vehicle Details

Chassis Number	W0LPF2DS9F*******
Specification	GCC Specification
Make	Opel
Model	Astra
Model Year	2015
Color	Blue
Mileage	260476 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE , REAR RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR SCRATCHES	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR FULLY MUDDY OILY PORTION DENT, REQUIRED PROPERLY STEAM WASH	الارضية
01.F Bumper	MISALIGN , GRILL DAMAGED , LOGO MISSING	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY OILY PORTION COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	FOR RECHEKE PROPERLY MAKE STEAM WASH	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK DRIPPING REFITTED, FULLY OILY DIRTY, OVERHEAT	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	OIL LEAK DRIPPING REFITTED FULLY OILY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

CAR CHECK

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Tail Light	LEFT SIDE PORTION CRACKED	الضوء الخلفي
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Interior Condition		الحاله الداخليه
07.A Other	CENTER CONSOLE BOX SLIDING COVER STRIP MISSING	اخري
07.B AC Condition	LOW COOLING	المكيف
07.C Power Window Switch And Glass	MAIN SWICTH RIGHT SIDE LOOSE , NOT WORKING	مفتاح النافذه و الزجاج
07.D Roof Ceiling	LOOSE	بطانه السقف
07.E Sun Visor	BOTH SIDE MIRROR COVER MISSING	حاجب الشمس
07.F Door Panel	WORN OUT	لوحة بطانة الباب
07.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.H Gear Shifting Lever	KNOB PORTION DAMAGE	ذراع نقل السرعات
07.I Engine Start Button	KEY BUTTON DAMAGED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae