CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934036
Transaction Date	02 Nov 2026, 16:53:10
Site Name	840 - Emirates Auctions
Transaction Number	20457545 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WBAKR0108F*******
Specification	GCC Specification
Make	BMW
Model	X5
Model Year	2015
Color	White
Mileage	80360 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT FIBER PAINT NOT CHECK,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE PORTION REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED MUDDY MINOR DENT	الارضية
01.F Bumper	MISALIGN, FRONT INNER GRIIL MISSING , EXTRA LIGHT COVER DAMAGED	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , REFITTED	غطاء المحرك
01.H Trunk	SWITCH MELTED WORN OUT , PORTION REPAIRED REPAINTED,NOT OPEN	صندوق
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Other	WIRING OPEN LOOSE UNSAFE	اخري
03.B Engine Visual Condition	NOT START ALL SYSTEM NOT CHECK , OIL LEAK REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION CRACK	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED , REFITTED , OIL LEAK , PARTS GETTING RUSTY / HOUSING BOLT MISSING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2023 DRY CRACK	الاطار الامامي
06.B Rear Tyre	2023 DRY CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK , LEFT SIDE BRACKET DAMAGED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH CRACKED	فرامل اليد
08.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	REFITTED	
09.B Arms	BUSHES DRY CRACK	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
09.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY , CENTER CONSOLE BOX SLIDING COVER DAMAGED	اخري
10.B AC Condition	NOT CHECKED	المكيف
10.C Roof Ceiling	LOOSE	بطانه السقف
10.D Door Panel	WORN OUT	لوحة بطانة الباب
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	SIGN OF WATER MIX WITH OIL / WATER EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae