

Queue Number 2850875

Transaction Date 09 Oct 2026, 16:35:16

Site Name
840 - Emirates AuctionsTransaction Number
21156184 (CC10013) (CC10025)

Vehicle Details

Chassis Number	SJKDH5CP2H*****
Specification	GCC Specification
Make	Infiniti
Model	QX 30
Model Year	2017
Color	Grey
Mileage	145740 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED CHECK VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Trunk	REPAINTED PORTION REPAIRED ,LUGGAGE SHADE MISSING , PART COVER MISSING	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	MUDDY , DIRTY , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition الجير

04.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
06.B Tail Light	RIGHT SIDE CRACK	الضوء الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	الزرع
07.B Other	SUSPENSION PARTS REFITTED	اخرى
08 Interior Condition		الحالة الداخلية
08.A Mirror	RIGHT SIDE ADJUSTMENT , FOLDING NOT WORKING	المرآيا
08.B AC Condition	OK	المكيف
08.C Power Window Switch And Glass	SWITCH PORTION FADED	مفتاح النافذه و الزجاج
08.D Roof Ceiling	PORTION LOOSE	بطانة السقف
08.E Sun Visor	RIGHT SIDE MIRROR COVER PORTION DAMAGED	حاجب الشمس
08.F Door Panel	COVER PORION LOOSE	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae