

Queue Number 2870327

Transaction Date 15 Oct 2026, 16:43:30

Site Name
840 - Emirates AuctionsTransaction Number
61243154 (CC10009) (CC10019)

Vehicle Details

Chassis Number	WBSGZ0101A*****
Specification	GCC Specification
Make	BMW
Model	X6
Model Year	2010
Color	White
Mileage	100477 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECKED , LEFT SIDE PORTION CRACK	مدكار
01.B Paint	BODY PORTION REPAINTED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COMPLETELY COVERED MUDDY OILY,CHECKED VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN , HOCK COVER MISSING	دعامية
01.F Bonnet	REPAINTED REFITTED	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPOLETELY COVERED OILY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	OIL LEAK DRIPPING REFITTED	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK REFITTED	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2021 EXPIRED & RIGHT SIDE 2022 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 WORN OUT	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Interior Condition		الحالة الداخلية
07.A Other	CENTER CONSOLE BOX COVER DAMAGED	اخرى
07.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING ,PROPERLY & CENTER MIRROR BACK COVER MISSING	المرآيا
07.C AC Condition	OK , GRILL PORTION LOOSE , REAR GRILL ADJUSTMENT MISSING	المكيف
07.D Dash Board	LEATHER REPLASD	لوحة القيادة
07.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
07.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae