CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934024
Transaction Date	02 Nov 2026, 09:35:55
Site Name	840 - Emirates Auctions
Transaction Number	38082118 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JD1GM10024*******
Specification	GCC Specification
Make	Daihatsu
Model	Sirion
Model Year	2004
Color	Pink
Mileage	259391 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	3

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Doors	REAR LEFT QUARTER GLASS MISSING.	أبواب
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Pillars	PILLAR OUTER PANEL ROCKER PANEL REPAIRED.	القوائم
01.F Door Handle &Lock	OUTER HANDLE BROKEN	مقابض الأبواب والأقفال
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS REAR BOTH SIDE CHASSIS EXTENSION REPAIRED DENT GETTING RUSTY.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE EXPIRED CRACKED WORN OUT.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE EXPIRED CRACKED WORN OUT.	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B Mirror	LEFT SIDE DAMAGED.	المرايا
11.C AC Condition	NOT CHECKED .	المكيف
11.D Dash Board	PORTION DAMAGED.	لوحة القياده
11.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae