CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2945031
Transaction Date	06 Nov 2026, 16:10:15
Site Name	840 - Emirates Auctions
Transaction Number	63321852 (CC10013) (CC10013)



Vehicle Details

Chassis Number	MAJTJ2ZD4F*******
Specification	GCC Specification
Make	Ford
Model	Figo
Model Year	2015
Color	White
Mileage	143370 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT DAMAGED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.E Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.F Trunk	NOT CHECK	صندوق
01.G Fuel Tank	DENT	خزان الوقود
01.H Sign of back accident	BACK PANEL, QUATER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	REAR RIGHT SIDE EXTENSION OUTER REPAIRED BEND / DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Exhaust System		نظام العادم
04.A Other	DENT	اخري
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2023 DRY CRACK	الاطار الامامي
06.B Rear Tyre	2023 DRY CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACK	الضوء الخلفي
07.C Indicator & Hazard light	FRONT LEFT WORN OUT	الاشارات
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	ALL BUSHES DRY CUT	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS RUSTY, SIGN OF FLOODED	اخري
10.B AC Condition	NOT CHECKED	المكيف
10.C Dash Board	GETTING FADED PORTION WORN OUT CRACK	لوحة القياده
10.D Sun Visor	LOOSE	حاجب الشمس
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae