



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jan 2023, 14:06:47
Transaction Number	54645558 (CC10006)	Queue Number	657303



Chassis Number	MA3ZE8A15H0459810
Engine Number	
Vehicle Class	Car
Manufacturer	Suzuki
Model	Ertiga
Model Year	2017
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	NOT CHECK	حالة الجير النظري
02 Interior Condition		الحاله الداخليه
02.A AC Condition	NOT CHECK	المكيف
02.B Odometer reading	NOT CHECK	قراءة عداد المسافات
03 Engine Condition		المحرك
03.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,	حالة المحرك النظري
04 Lights		الاضاءة
04.A Head Light	LEND PORTION FADED,ALL LIGHS NOT CHECK	الاضاءة الرئيسية
05 Suspension System		ممتص الصدمات
05.A Arms	LOWER ARM BUSHES CRACKED	ازرع
06 Body		جسم المركبة
06.A Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
06.B Bumper	MISALIGN	دعامية

DEFECT	REMARKS	
06.C Paint	BODY MINOR DENT SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.B Axle	BOOT CUT	اكسلات
08 Tires and Rims Condition		الاطارات
08.A Rear Tyre	BOTH SIDE 2019 CRACKED,WORN OUT	الاطار الخلفي
08.B Front Tyre	LEFT SIDE 2019 CRACKED,RIGHT SIDE 2017 CRACKED EXPIRED	الاطار الامامي
09 Chassis Condition		الشاصي
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.