CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3012677
Transaction Date	20 Nov 2026, 16:37:11
Site Name	840 - Emirates Auctions
Transaction Number	62275989 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WBA4A5103G*******
Specification	GCC Specification
Make	BMW
Model	428
Model Year	2016
Color	White
Mileage	62662 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN,PORTION CRACKED ,COVER HOOK MISSING	دعامية
01.E Windshield	FRONT SPOT CRACKED	زجاج
01.F Bonnet	REPAINTED,PORTION REPAIRED	غطاء المحرك
01.G Trunk	REPAINTED,PORTION REPAIRED,REFITTED,SWITCH WORN OUT MELTED	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VSISBLE AREA ONLY/OK	الشاسيه
02.B Chassis Number	MANUFACTURE STICKER MISSING	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	DELAY STARTING /SHAKING REFITTED OIL WET , WIRING LOSSE OPEN UNSAFE	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
05 Exhaust System		نظام العادم

Condition	Remarks	الحالة
05.A Catalytic Converter	CUT REWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING INNER JOINT SHEET MISSING	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
07.C Rims Condition	MINOR DENT,SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CUT	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT	اخري
10.B AC Condition	OK	المكيف
10.C Audio	NOT WORKING ,SCREEN DAMAGED	صوتيات
10.D Roof Ceiling	PORTION LOOSE	بطانه السقف
10.E Sun Visor	LEFT SIDE GLASS COVER PORTION DAMAGED	حاجب الشمس
10.F Door Panel	PORTION WORN OUT MELTED	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae