

Queue Number 2837249

Transaction Date 07 Oct 2026, 13:19:53

Site Name
840 - Emirates AuctionsTransaction Number
82363412 (CC10021) (CC10019)

Vehicle Details

Chassis Number KL1PJ5C54A*****
 Specification GCC Specification
 Make Chevrolet
 Model Cruze
 Model Year 2010
 Color Red
 Mileage N/A NA
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES, PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامة

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسية
--------------	--	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition	المقاعد
--------------------	---------

04.A Seat Condition	COVER PORTION CRACKED	حالة المقاعد
---------------------	-----------------------	--------------

05 Transmission Condition	الجير
---------------------------	-------

05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

05.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

06 Tires and Rims Condition	الاطارات
-----------------------------	----------

06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
-----------------	-----------------	----------------

Condition	Remarks	الحالة
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطمباير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS RUSTY, SIGN OF WATER FLOODED	اخرى
10.B AC Condition	NOT CHECKED	المكيف
10.C Audio	MISSING	صوتيات
10.D Dash Board	GETTING FADED PORTION WORN OUT CRACKED	لوحة القيادة
10.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae