



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>17 Oct 2021, 17:56:47</b> |
| Transaction Number | <b>79725342 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>5N1AR1N73BC602510</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Nissan</b>            |
| Model            | <b>Pathfinder</b>        |
| Model Year       | <b>2011</b>              |
| Color            | <b>White</b>             |
| Mileage          | <b>145125 Km</b>         |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>6</b>                 |
| Specification    | <b>GCC Specification</b> |

| DEFECT                           | REMARKS  |                    |
|----------------------------------|--|--------------------|
| <b>01 Body</b>                   |  | <b>جسم المركبة</b> |
| 01.A Paint                       | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY     | الصبغ              |
| 01.B Doors                       | REAR LEFT SIDE REPAIRED & REPAINTED                        | أبواب              |
| 01.C Rusty                       | UNDER BODY PARTS, SUSPENTION , CHASSIS FRAME GETTING RUSTY | صدأ                |
| 01.D Bumper                      | REPAINTED  | دعامية             |
| <b>02 Chassis Condition</b>      |  | <b>الشاشي</b>      |
| 02.A Chassis                     | OK   | الشاسيه            |
| <b>03 Engine Condition</b>       |  | <b>المحرك</b>      |
| 03.A Engine Condition            | OIL LEAK   | حالة المحرك        |
| 03.B Mount                       | BUSHES CRACKED   | كرسي               |
| <b>04 Seats Condition</b>        |  | <b>المقاعد</b>     |
| 04.A Seat Condition              | OK   | حالة المقاعد       |
| <b>05 Transmission Condition</b> |  | <b>الجير</b>       |
| 05.A Road Test                   | NOT CHECK  | فحص علي الطريق     |

| DEFECT                                       | REMARKS  |                        |
|--|--|------------------------|
| 05.B DIFFERENTIAL                            | BUSHES CRACKED   | الدفرنشيل              |
| <b>06 Wipers and Arms</b> المساحات           |  |                        |
| 06.A Wiper Arm &Blade                        | WORN OUT   | ازرع المساحات والشفرات |
| <b>07 Lights</b> الاضاءة                     |  |                        |
| 07.A Head Light                              | OK   | الاضاءة الرئيسية       |
| 07.B Other                                   | OK   | اخرى                   |
| 07.C Warning Light                           | SRS ON   | ضوء تحذير              |
| <b>08 Brake Condition</b> الفرامل            |  |                        |
| 08.A Disc&Drum                               | GETTING RUSTY  | دسك ووطنابير الفرامل   |
| <b>09 Tires and Rims Condition</b> الاطارات  |  |                        |
| 09.A Front Tyre                              | BOTH SIDE 2021   | الاطار الامامي         |
| 09.B Rear Tyre                               | BOTH SIDE 2021   | الاطار الخلفي          |
| <b>10 Suspension System</b> ممتص الصدمات     |  |                        |
| 10.A Suspension Subframe                     | SUSPENTION SUB FRAME GETTING RUSTY                               |                        |
| 10.B Arms                                    | FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS<br>BUSHES CRACKED | ازرع                   |
| <b>11 Steering Condition</b> المقود          |  |                        |
| 11.A Axel                                    | INNER BOOT CRACKED   | اكسلات                 |
| 11.B Tie Rod End                             | BUSHES CRACKED   | مؤخرة الرودادات        |
| 11.C Steering Boot                           | BOOT CUT & LEAKING   | ربلة المقود            |
| <b>12 Interior Condition</b> الحالة الداخليه |  |                        |
| 12.A Power Window Switch                     | REAR BOTH SIDE CONTROL SWITCH NOT WORKING<br>PROPERLY            | مفتاح النافذه          |
| 12.B Mirror                                  | OK   | المرايا                |
| 12.C Odometer reading                        | 145126 KM  | قراءة عداد المسافات    |
| 12.D AC Condition                            | OK   | المكيف                 |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.