CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2972879
Transaction Date	11 Nov 2026, 17:02:57
Site Name	840 - Emirates Auctions
Transaction Number	33895604 (CC10009) (CC10019)



Vehicle Details

Chassis Number	SALGA2DFXE*******
Specification	GCC Specification
Make	Range Rover
Model	HSE
Model Year	2014
Color	White
Mileage	143199 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY MINOR DENT SCRATCHES,	الصبغ
01.B Doors	REAR BOTH SIDE REFITTED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS FULLY COVERED, COVER PORTION LOOSE,	الارضية
01.E Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.F Trunk	AUTO SWITCH NOT WORKING PROPERLY	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED, MUDDY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH REMOVE ALL UNDER COVER FOR RECHECK PROPERLY	اخري
02.C Chassis Number	CHECKED ON STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OVERHEAT/OIL LEAK DRIPPING OPEN REFITTED HOLE COVER MISSING	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR OIL LEAK OPEN REFITTED JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Lights		الاضاءة

Condition	Remarks	الحالة
05.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	FRONT LEFT SIDE AIR DUMPPER COVER DAMAGED	ممتص الصدمات
06.B Arms	BUSHES CRACKED	ازرع
06.C Other	SUSPENSION REFITTED	اخري
07 Interior Condition		الحاله الداخليه
07.A Other	REAR CENTER CONSOLE BOX LEATHER PORTION DAMAGED	اخري
07.B Mirror	BOTH SIDE FOLDING ADJUSTMENT NOT WORKING PROPERLY	المرايا
07.C Roof Ceiling	LOOSE	بطانه السقف
07.D Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
07.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08 Engine Cooling System		نظام تبريد المحرك
08.A Radiator Condition	COOLANT WATER LEAK	حالة المبرد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae