CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2922679
Transaction Date	29 Oct 2026, 13:23:21
Site Name	840 - Emirates Auctions
Transaction Number	53567405 (CC10013) (CC10019)



Vehicle Details

Chassis Number	3FA6P0H74F*******
Specification	GCC Specification
Make	Ford
Model	Fusion
Model Year	2015
Color	Black
Mileage	138461 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED DIRTY MUDDY MINOR DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Door Handle &Lock	FRONT LEFT SIDE HANDLE LOCK COVER MISSING	مقابض الأبواب والأقفال
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY DIRTY PORTION GETTING RUSTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH FOR RECHECK	اخري
02.C Chassis Number	VIN CHECK DOOR POST STICKER ONLY	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL WET , REFITTED , PARTS GETTING RUSTY , MISFIRING , SHAKING , ABNORMAL NOISY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT BOTH SIDE SEAT ADJUSTMENT NOT WORKING	حالة المقاعد
05 Exhaust System		نظام العادم

Condition	Remarks	الحالة
05.A Other	MINOR DENT	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	GEAR FAULT NOT SHIFTING PROPERLY JERKING , OPEN REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Warning Light	WARNING MESSAGE ON DISPALAY	ضوء تحذير
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY	دواسة الفرامل
09.B Hand Brake	SWITCH FADED	فرامل اليد
10 Suspension System		ممتص الصدمات
10.A Arms	ARM BUSHES DRY CRACK	ازرع
10.B Ball Joint	BOOT CUT	مفصل كروي
11 Steering Condition		المقود
11.A Tie Rod End	BOOT CUT	مؤخرة الرودات
12 Interior Condition		الحاله الداخليه
12.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED & CENTER CONSOLE BOX COVER WORN OUT	اخري
12.B Mirror	CENTER MIRROR PORTION FADED	المرايا
12.C AC Condition	OK	المكيف
12.D Power Window Switch And Glass	FRONT LEFT SIDE AUTO SWITCH PORTION DAMAGED	مفتاح النافذه و الزجاج
12.E Dash Board	PORTION CRACKED	لوحة القياده
12.F Roof Ceiling	PORTION LOOSE	بطانه السقف
12.G Steering Wheel and control buttons	WORN OUT & SWITCH PORTION DAMAGED	عجلة القيادة وازرار التحكم
12.H Gear Shifting Lever	DUST COVER PORTION DAMAGED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**