



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Nov 2022, 12:25:32
Transaction Number	31349701 (CC10006)	Queue Number	631130



Chassis Number	5XYPGDA50KG494501
Engine Number	
Vehicle Class	Car
Manufacturer	Kia
Model	Sorento
Model Year	2019
Color	Violet
Mileage	25063 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Sign of side accident		وجود مؤشر لحادث في الجانب
01.B Floor	UNDER FLOOR COVERD, CHECKED ONLY VISIBLE AREA & COVER PORTION DAMAGED	الارضية
01.C Bumper	MISALIGN	دعامية
01.D Doors	FRONT LEFT SIDE REPAINTED & REFITTED	أبواب
01.E Pillars	LEFT SIDE A/PILLAR OUTER PORTION REPAIRED, REPAINTED	القوائم
01.F Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
01.G Fenders	FRONT LEFT SIDE REPLACED & RIGHT SIDE REPAINTED	مدكار
01.H Bonnet	PORTION REPAIRED REPAINTED & REFITTED	غطاء المحرك
01.I Other	FRONT FENDER FRAME, RADITOR SUPORT, BUMPER FRAME, WHEEL ARCH REPAIRED	اخرى
01.J Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي

DEFECT	REMARKS	
03 Battery Condition		حالة البطارية
03.A Battery bracket	MISSING	حامل البطارية
04 Chassis Condition		الشاسي
04.A Chassis	FRONT LEFT SIDE CHASSIS OUTER SKIRT REPAIRED	الشاسيه
04.B Other	VIN STICKER SCRATCHES	اخرى
05 Transmission Condition		الجير
05.A Gear Box Mount	BRACKET DENT	كرسي الجير
05.B Road Test	NOT CHECK	فحص علي الطريق
05.C Visual Gear Box Condition	OPEN, REFITTED, DENT & MINOR OIL LEAK	حالة الجير النظري
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
07 Interior Condition		الحاله الداخليه
07.A Air Bag	LEFT SIDE BOTH DAMAGED & MISSING	وسائد هوائية
08 Engine Condition		المحرك
08.A Visual Engine Condition	OK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Custom Certificate :	13229982
Chassis No :	5XYPGDA50KG494501
Vehicle Make :	KIA
Vehicle Model :	SORENTO
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Red
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	40333 Kms.
Origin : United States	Model Year : 2019
Gear Type : Automatic	Engine Size : 3300 CC
Engine No : NIL	Horse : --
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 7
G. V. W. : 2300 Kgs.	Empty : 2000 Kgs.
	Weight :

Certificate Number :	5-MUM-2022-18172611		
Inspection Date :	24-11-2022		
Certificate Print Date :	24-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Al Mumayaz Vehicle Inspection		
Vehicle Testing Center :	Al Mumayaz Al Barsha		
Total Time Taken :	11 min 6 sec		
Appointment Ref Number :	--		
Start Time :	13:06	End Time :	13:17
Lane :	02	Token No. :	163
Attempt :	2	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

6722 KM	692 L	2360 AED	1.7 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks: FRONT LEFT SIDE FENDER FRAME AND OUTER SKIRT REPAIRED .

Payment Details

Inspection Performed by MZ70	Payment Method Cash	Transaction Number 18172611	Service Fees AED 70 Collected on 24/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by MOHAMAD GHASSAN ISKANDARANI

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

